From: Cook, David <David.Cook@WestonSolutions.com>

Sent: Wednesday, August 30, 2017 2:39 PM

To: Delgado, Eric

Cc: Smalley, Bryant; Foster, Althea; Janine.Latham@WestonSolutions.com; Restivo, Angela; McDowell,

Justin; Buchanan, Kayla; Meyer, John; Coltrain, Katrina

Subject: NPL Site Map 20170830 1300

Attachments: NPL_Federally_Declared_Only_Harvey_20170830_1300.pdf; Resources Locations Map_Harvey_

20170830.pdf; Facility Statuses_20170830_0519.xlsx

Good afternoon,

Please find the attached PDF, Resources Locations PDF and DW/WW status spreadsheet.

Thanks,



David Cook

Programmer / GIS Analyst

Weston Solutions, Inc.

2705 Bee Cave Rd, Suite 100 Austin, Texas 78746


(512) 651-7152 Direct

(512) 970-8836 Cell

(512) 651-7101 Fax

david.cook@WestonSolutions.com

CONFIDENTIALITY: This email and attachments may contain information which is confidential and proprietary. Disclosure or use of any such confidential or proprietary information without the written permission of Weston Solutions, Inc. is strictly prohibited. If you received this email in error, please notify the sender by return e-mail and delete this email from your system. Thank you.






National Hurricane Center

~ Forecast Track

Tropical Storm/


US EPA Region 6 National Priority List (NPL) Sites in Federally Declared Counties/Parishes

Hurricane Harvey Response National Weather Service Public Advisory #41A 1300 CDT 20170830





EPA GIS Printed: 1:58:37 PM 8/30/2017



DW - Total # of Systems: 4510

| STATUS | NUMBER OF SYSTEMS |
|---|-------------------|
| Contact Pending | 56 |
| Out of Contact | 32 |
| On generator – lost pressure | 5 |
| No problems | 210 |
| On generator – never lost pressure | 15 |
| No Status | 4155 |
| Lost pressure & or Treatment | 7 |
| Site visit needed | 2 |
| Lifted boil water notice due to negative bacteria samples. Normal Ops resumed | 8 |
| Not Operating | 20 |

WW - Total # of Systems: 2466

| STATUS | NUMBER OF SYSTEMS |
|--|-------------------|
| Contact Pending - Phone evaluation only | 41 |
| Out of Contact - phone evaluation only | 6 |
| No Problems | 250 |
| No Status | 2127 |
| Waste Water Treat. Plant and/or Collection on Generator or bypass pumps for Lift Station | 16 |
| Waste Water Treat. Plant and/or Collection non operational no Sanitary Sewer Overflow | 19 |
| WWTP and/or Collection Partially Operational Sanitary Sewer Overflow | 7 |

^{*}Response Manager Sync Time Used For This Dataset: 20170830 @ 0519